


1/24

FIG. 1



2/24

FIG. 2B





FIG. 2A



3/24

FIG. 3




FIG. 4






FIG. 5






TORQUE TRANSMISSION TIME

6/24

FIG. 6




7/24

**FIG. 7A****FIG. 7B****FIG. 7C**


8/24

FIG. 8




9/24

FIG. 9




10/24

FIG.10




11/24

FIG.11




12/24

FIG.12




13/24

FIG.13




14/24

FIG.14




15/24

FIG.15




16/24

FIG.16




**FIG. 17**




18/24

FIG. 18




19/24

FIG.19




20/24

FIG.20




21/24

FIG.21




22/24

FIG.22



23/24

FIG.23



24/24

FIG.24A




FIG.24B

